



Technical Service Bulletin

TB17 **Affected Models:** 1990-91 Nissan 300ZX Turbo

Problem: Clutch Slippage

Solution: Install new master cylinder and return spring

Ref. Bulletin: Nissan MT92-006

Nissan recommends replacing both the clutch master cylinder and the pedal return spring with new part numbers to eliminate clutch slipping problems.