

## Technical Service Bulletin

---

<b>TB34 Affected Models:</b>	Releasers that must be pressed on bearing carrier.
<b>Part Number:</b>	Sachs Clutch Kits using SB770 Releaser
<b>Problem:</b>	Possibility of installing the bearing incorrectly.
<b>Solution:</b>	Specific direction on the correct installation of the releaser.

It is possible to install the releaser incorrectly on the bearing carrier, and install the releaser backwards. The correct installation is when the rounded hard steel side of the releaser faces the diaphragm spring fingers of the pressure plate. When the releaser is installed backwards, the stamped steel side of the bearing (which usually has part numbers stamped it) faces the pressure plate. If installed backwards, the releaser will make noise immediately after installation.

