



Technical Service Bulletin

TB28 Affected Models:	1992 – 1995 Chevrolet and GMC trucks with 6.5L Diesel Engine
Kit Number:	K70054-01 Clutch Kit
Problem:	Clutch Kit Application without Dual Mass Flywheel
Solution:	Install New Dual Mass Flywheel DMF0901

If the vehicle being serviced is equipped with a solid flywheel, the vehicle has been altered since it was manufactured. All 1992 through 1995 vehicles with a 6.5L diesel engine were originally equipped with a Dual Mass Flywheel from the factory. If the vehicle has a solid flywheel it has been changed since its production. The change can be identified by a dampened disc (a disc with springs in the center of the hub) being removed from the vehicle. The kit K70054-01 has a solid hub disc (no springs on the disc). The Sachs Kit K70054-01 **will not work** with a vehicle that has had the solid flywheel conversion. Installation of a Sachs Dual Mass Flywheel DMF0901 and a K70054-01 Clutch Kit will restore the vehicle to its originally designed form.

SACHS NORTH AMERICA 909 Crocker Road Westlake, OH 44145-1095
Technical Hotline 1-800-321-0784, Ext. 110
8:00 AM - 5:00 PM EST