



Technical Service Bulletin

TB33 Affected Models: Various

Kit Number: K0058-01, K0058-01HD

Subject: The disc in the kit is approximately 3/8 inch smaller in diameter than the pressure plate.

The disc enclosed in the kit K0058-01 is an 11 ½ inch disc and the pressure plate is an 11 7/8 inch unit. This is a replacement part with a smaller diameter disc. There is no problem with the kit. The disc lining material has been reduced in width to effectively increase clamp load and transmit more torque.

SACHS NORTH AMERICA 909 Crocker Road Westlake, OH 44145-1095
Technical Hotline 1-800-321-0784, Ext. 110
8:00 AM - 5:00 PM EST